

All times in UTC

**GÖTEBORG/Landvetter AD (ESGG) –  
Banarbete/begränsningar RWY 03/21**

*Ersätter AIP SUP 12/2019*

Under perioden 5 MAJ – 30 MAJ 2019 genomförs banarbeten av den mittersta delen av RWY 03/21.

RWY 03/21 är stängd nattetid följande tider:

5 – 10 MAJ 2000-0359  
12 – 17 MAJ 2000-0359  
19 – 24 MAJ 2000-0359  
26 – 30 MAJ 2000-0359

ILS CAT II/III är ur funktion under perioden  
5 MAJ 2000 – 30 MAJ 0400

Ytterligare begränsningar:

RWY centrumlinjeljus ur funktion.

Centrumlinjeljus för TWY C, D, E, mellan RCL och bankant, ur funktion.

Dagermarkeringarna RCL och intaxningslinjerna för TWY C, D och E kan vara otydliga.

Längsgående asfaltsskarv (18 mm) kan förekomma på rullbanan.

Övrigt:

Förseningar kan uppstå vid öppning av manöverområdet.

**GÖTEBORG/Landvetter AD (ESGG) –  
Work/limitation RWY 03/21**

*Replaces AIP SUP 12/2019*

During the period 5 MAY – 30 MAY 2019 work will take place in mid-section of RWY 03/21.

RWY 03/21 is closed nightly following hours:

5 – 10 MAY 2000-0359  
12 – 17 MAY 2000-0359  
19 – 24 MAY 2000-0359  
26 – 30 MAY 2000-0359

ILS CAT II/III unserviceable during the period  
5 MAY 2000 – 30 MAY 0400

Further limitations:

RWY centre line lights out of service.


Centre line lights TWY C, D, E, between RCL and RWY edge, out of service.

Daymarkings RCL and CL TWY C, D and E between RCL and RWY edge poor visibility.

Asphalt joints (18 mm) running lengthwise on the runway may occur.

Other:

Minor delay may occur during opening of manoeuvre area.



- SLUT / END -