

List of waypoints and significant points at RONNEBY (ESDF)

WPT	Coordinates
RW01	561524.95N 0151545.17E
RW19	561639.45N 0151605.63E
DF531	562546.0N 0152743.1E
DF532	563127.5N 0152011.0E
DF534	562207.1N 0151735.9E
DF550	560447.6N 0152152.6E
DF711	560617.4N 0150413.6E
DF712	560036.8N 0151143.2E
DF713	560956.1N 0151414.9E
DF850	562716.6N 0150954.6E
EKLOV	562631.6N 0151849.0E
SUXEM	560532.8N 0151303.3E
TEMLI	564041.5N 0152301.7E