



<b>Communication failure</b> NIL	<table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>RWY NR</th> <th>THR ELEV</th> <th>PAPI (MEHT)</th> </tr> </thead> <tbody> <tr> <td>09</td> <td>1172.7 ft</td> <td>Left/3.00° (50 ft)</td> </tr> <tr> <td>27</td> <td>1177 ft</td> <td>Left/3.00° (50 ft)</td> </tr> </tbody> </table>	RWY NR	THR ELEV	PAPI (MEHT)	09	1172.7 ft	Left/3.00° (50 ft)	27	1177 ft	Left/3.00° (50 ft)	<b>Entry / exit point</b> NIL  <b>Holding</b> NORTH: Hold over Western shoreline of Nordsjön, north of point 620519N 0142715E SOUTH: Hold over south part of lake Vallsjön, south of point 620029N 0142746E
RWY NR	THR ELEV	PAPI (MEHT)									
09	1172.7 ft	Left/3.00° (50 ft)									
27	1177 ft	Left/3.00° (50 ft)									
<b>Remark/Warning</b> NIL	<b>Legend</b> See GEN 2.3										

Reverse side intentionally blank