

All times in UTC

**GÄLLANDE AIP SUPPLEMENT**

Följande AIP Supplement är gällande den  
10 JAN 2019.

**VALID AIP SUPPLEMENTS**

The following AIP Supplements are valid on  
10 JAN 2019.

<b>No/Year</b>	<b>Subject – Title</b>
3/2019	Valid AIP Supplements
2/2019	Temporary obstacles with long duration
1/2019	Temporary restricted areas – KABLA and VARVEK
122/2018	GÖTEBORG/Landvetter AD (ESGG) – Work/limitation RWY 03/21
121/2018	Temporary restricted area Gålö B and temporarily extended activity in R96 Berga and R71C Nättarö
118/2018	Temporary restricted area – Tumba Bruk
117/2018	Temporary restricted area – Stockholm/Huddinge
115/2018	GÖTEBORG/Landvetter AD (ESGG) – Parts of apron closed
114/2018	GÖTEBORG/Landvetter AD (ESGG) – Temporary changes of procedures due cranes
110/2018	GÖTEBORG/Landvetter AD (ESGG) – Communication failure procedure for aircraft without ADF
108/2018	Conversion to 8,33 kHz channel spacing postponed
106/2018	GÖTEBORG/Landvetter AD (ESGG) – Updated chart
102/2018	VIDSEL AD (ESPE) – TWY A2 closed
93/2018	Temporary danger areas Västervik, Byxelkrok and Arkösund
39/2018	KARLSTAD AD (ESOK) – OM RWY 03 U/S
26/2018	GÖTEBORG/Landvetter AD (ESGG) – Temporary stand 19A
24/2018	UMEÅ AD (ESNU) – Temporary changes of procedures due crane
17/2018	Umeå VOR/DME UME, degraded performance
13/2018	STOCKHOLM/Bromma AD (ESSB) – Temporary changes of procedures due cranes
9/2018	STOCKHOLM/Skavsta AD (ESKN) – PAPI out of service
87/2017	SÅTENÄS AD (ESIB) – RWY 01/19 closed
38/2017	GÖTEBORG/Landvetter AD (ESGG) – Centreline lights out of service
30/2015	Rules of the air
47/2012	LYCKSELE AD (ESNL) – TRID out of service

– SLUT / END –